



SERVICE ALERT

NO.: 1346 Revision A

TO: Garmin Aviation Service Centers and Owner/Operators of all Cirrus Perspective®, Embraer Prodigy™, G1000, G2000, G3000, G5000, G900X, G950 products

DATE: July 29, 2013

SUBJECT: Incorrect Hold Turn

AFFECTED PRODUCTS

All Cirrus Perspective®, Embraer Prodigy™, G1000, G900X, and G950 systems with GDU Software Version 13.XX and all G2000, G3000, and G5000 products with GDU/GTC software versions up to and including software version 3.15 are affected by this alert.

DESCRIPTION

In some instances when flying a hold pattern, the autopilot may turn the wrong direction at the third crossing (and any subsequent crossing thereafter) of the hold waypoint. This will result in an approximately 270 degree turn toward the wrong (unprotected) side of the holding waypoint.

PILOT ACTION

While flying holding patterns with the autopilot engaged, remain vigilant and ensure the autopilot maintains the aircraft on the intended course in assigned airspace. If the error condition occurs, select HDG mode and fly the hold by moving the heading bug, or disengage the autopilot and fly the hold manually. The autopilot may be engaged after leaving the hold.

RESOLUTION

This issue will be corrected in a future software release.

© Copyright 2013
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.