

GARMIN[®]

Navigation Data Alert

DATE: 17 September 2018

CYCLE: 1810, Effective 13 SEP 2018 to 11 OCT 2018

SUBJECT: Incorrect Inbound Holding Course and Leg Length

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect inbound holding course and leg length on the missed approach phase of the procedure:

Airport	Procedure	Error
SANC	VOR RWY 02 (S02)	The inbound course and leg length on the missed approach hold were incorrectly delivered as 016° and 1 minute. The correct inbound course and leg length are 223° and 4nm.

This alert applies to the 1810 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 1811 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."