

GARMIN[®]

Navigation Data Alert

DATE: 03 October 2018
CYCLE: 1810, Effective 13 SEP 2018 to 11 OCT 2018
SUBJECT: Incorrect Approach Transition and Procedure Turn

DESCRIPTION

Garmin has been made aware that the following procedures were delivered with an incorrect approach transition and procedure turn:

Airport	Procedure	Error
CYBR	ILS and LOC RWY 08 (108 & L08)	The procedures were delivered with an incorrect approach transition and procedure turn. YBR VOR/DME should be BR NDB.

This alert applies to the 1810 and 1811 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 1812 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."