



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTN Xi Series Owner and Operators
DATE: August 6, 2021
SUBJECT: GTN Xi Main Software Version 20.20 and GPS Software Version 8.2
CERTIFICATION AUTHORIZATION: FAA STC SA02019SE-D

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification of the FAA STC SA02019SE-D Master Drawing List GTN 6XX/ 7XX Part 23 AML STC, 005-00533-C0 Rev. 32 for the following:

GTN Xi Main Software Version 20.20:

- Added Smart Glide, a safety-enhancing feature that reduces pilot workload in the event of loss of engine power.



NOTE

The Smart Glide feature is compatible with the following Garmin LRUs:

- G500 TXi/G600 TXi/G700 TXi (v3.30)
- GI 275/GFC 500 (v2.40)
- GFC 600 (v2.80)



NOTE

This feature requires settings to be entered in configuration mode: GTN Setup > Navigation Features > Smart Glide Settings. This settings page has replaced "Glide Range Ring Settings" in previous versions of software. Glide Range Ring may be enabled without Smart Glide.

- Improved database acknowledgment process in installations with multiple GTN Xi / G500(H)/ G600/G700 TXi (sw v.3.30) LRUs. GTN #1 analyzes all databases from the other LRUs and provides a single point for acknowledgment when all are valid and current.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



NOTE

The other LRUs only stop for database confirmation if a problem exists that the pilot needs to acknowledge. The acknowledgment process for single GTN Xi installations remains the same.



NOTE

SD cards containing databases should be removed from the second GTN Xi series navigator and/or GDU TXi unit(s). If SD cards are desired to be retained, databases must be erased from the SD cards.

- Added option to allow the Instrument Self-test page to be bypassed at startup for cockpits where it is not needed.



NOTE

This setting can be enabled in configuration mode: GTN Setup > Main System > Self-test Page.

- Fixed an issue with GMA Recorder playback volume not retaining value set by pilot during flight.
- Changed label of “Enable ES” button on transponder menu to “ADS-B Out” to better reflect functionality.



NOTE

When “ADS-B Out” is enabled, shown by green bar, the unit commands the transponder to send ADS-B out data.

Additionally, the GPS/WAAS software is updating to 8.2 to address the MSAS range rate corrections issue identified in Garmin Service Advisory 20109 and restores MSAS to the set of allowed SBAS service providers.



NOTE

If MSAS was disabled by the user under Garmin Service Advisory 20109, it will need to be enabled after installing GPS/WAAS software v8.2. Refer to the applicable pilot's guide for instruction on how to enable MSAS.

PRODUCTS AFFECTED

GTN Xi systems installed under the GTN 6XX/7XX Part 23 AML FAA STC SA02019SE-D are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.