

## SERVICE ADVISORY

NO.: 1508 Rev B

### **SECOND NOTICE**

**TO:** All Garmin Aviation Service Centers and Owners/Operators of the Products Affected

**DATE:** April 21, 2015

**SUBJECT:** Discontinued Repair Service on Certain Apollo/II Morrow Products

---

#### **PRODUCTS AFFECTED**

This advisory is applicable to the following equipment:

- SL50 GPS Receiver
- SL60 GPS Receiver and VHF Comm Transceiver
- SL70 Mode C Transponder
- GSL71 UAT Control Panel

#### **DISCUSSION**

Effective June 30, 2015, repair services will be discontinued for the products listed above.

We sincerely regret discontinuing service or support on any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit [www.garmin.com/aviation](http://www.garmin.com/aviation) for your product replacement needs.