



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 1575 Rev A

**TO:** Owners/Operators of Record

**DATE:** November 23, 2015

**SUBJECT:** Flight Timer

---

### **PRODUCTS AFFECTED**

Garmin G1000(H), Cirrus Perspective, Embraer Prodigy, G900X, and G950 with GDU software versions 13.00 through 15.01 are affected.

### **ISSUE**

Using the checklist function may cause the flight timer to set back to zero during flight. The flight timer provides total flight time between avionics power cycles.

**NOTE**

Only the flight timer is affected. All other timers work as intended.

### **PILOT ACTION**

Do not rely on the flight timer to provide accurate flight time.

### **RESOLUTION**

A future software release will correct this issue.

© 2015 Garmin Ltd. or its subsidiaries.  
This work is licensed under a  
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.