



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record for the GTX 3000
DATE: August 05, 2016
SUBJECT: Software Version 3.20 available for GTX 3000 units (not applicable to G5000, G3000, G2000, G1000, G1000H, G950, G900X, Cirrus Perspective®, or Embraer Prodigy™ Integrated Flight Deck installations)
CERTIFICATION APPROVAL: TSO Authorization (see Service Bulletin SB 1642 for details)

COMPLIANCE

Optional - TSO Service Bulletin 1642 may be incorporated at the owner's discretion and is not warranty reimburseable.

PURPOSE

This Service Bulletin incorporates new unit Software Version 3.20 for GTX 3000 units. Software Version 3.20 incorporates the following functionality:

- Ensure proper CDU maintenance reporting in ProLine installations
- Ensure proper AFCS mode reporting in EHS registers when using the A429 AFCS input format

PRODUCTS AFFECTED

This bulletin is applicable to GTX 3000 units with software version 3.10 or previous software versions not installed in a Garmin Integrated Flight Deck system (G5000, G3000, G2000, G1000, G1000H, G950, G900X, Cirrus Perspective™, and Embraer Prodigy® Integrated Flight Deck Systems). The GTX 3000 current software version can be retrieved using the GTX install tool.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.