



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of GTX 3X5(R) Series Products
DATE: September 19, 2016
SUBJECT: GTX 3X5(R) Series Software Upgrade to Main Software Version 2.05 and ADS-B Software Version 2.05
CERTIFICATION APPROVAL: TSO

COMPLIANCE

Optional

PURPOSE

GTX 3X5(R) Series main software version 2.05 includes the following changes:

- Fixed issues with GPS altitude used for rotorcraft air/ground logic
- Field enabled feature for 3rd party transponder control
- Fixed bugs in TIS-A functionality
- Added configuration setting to allow the message alert (MSG) to not flash if desired
- Removed extraneous alerts for GPS Fault and GPS Keep Alive

GTX 3X5(R) Series ADS-B software version 2.05 includes the following changes:

- Improved update rate of external AHRS output over Bluetooth
- Added Optimized Legacy ADS-B format for 3rd party displays

PRODUCTS AFFECTED

All GTX 3X5(R) series products listed below that meet one or more of the following conditions are affected:

- interfaced to a 3rd party transponder controller
- interfaced to an external AHRS
- installed in rotorcraft

Model	Appliance P/N
GTX 335	011-03300-0()
GTX 335 NV	011-03300-2()
GTX 335 GPS	011-03300-4()
GTX 335R	011-03301-0()
GTX 335R GPS	011-03301-4()
GTX 345	011-03302-0()
GTX 345 GPS	011-03302-4()
GTX 345R	011-03303-0()
GTX 345R GPS	011-03303-4()

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.