



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 14 March 2018

Subject: Sharjah, UAE
Sharjah Intl (OMSJ)
IVURO 2Q [IVUR2Q]
Cycle 1803 and 1804

Turn direction coded incorrectly

Jeppesen NavData for cycle 1803 and 1804, effective 1 Mar 2018 and 29 Mar 2018 respectively, contains an incorrectly coded turn direction on the IVURO 2Q [IVUR2Q] departure for Sharjah Intl; Sharjah, UAE (OMSJ). The left turn direction on the segment to SJ481 does **not** apply. The segment should be straight to SJ481.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 1805, effective 26 Apr 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Sharjah, UAE (OMSJ) chart 10-3 dated 26 JAN 2018 (EFF 1 FEB) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.