

SERVICE ADVISORY

NO.: 1822 Rev A

TO: Owners and Operators of Garmin G3000 and G5000 systems installed in Cessna

Citation CJ2+, Citation CJ3+, Citation M2, Citation Latitude, Citation Sovereign, and

Citation X+ aircraft

DATE: April 25, 2018

SUBJECT: DME/DME Navigation

PRODUCTS AFFECTED

G3000 and G5000 systems installed in Cessna Citation CJ2+, Citation CJ3+, Citation M2, Citation Latitude, Citation Sovereign, and Citation X+ aircraft with GDU/GTC Software Versions 4.01 to 6.57 are affected.

ISSUE

Adding a DME to the NOTAM NAVAIDS list may cause the Navigation Map to reset.

NOTE

If this problem occurs, no misleading information is displayed.

PILOT ACTION

Do not add a DME to the NOTAM NAVAIDS list. Do not enable DME/DME, instead rely on GPS position when flying within 200 nm of a NOTAMed DME.

RESOLUTION

This issue has been fixed in GDU/GTC Software Versions 20.70 and later.

© 2018 Garmin Ltd. or its subsidiaries.

This work is licensed under a

Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.