



JEPPESEN®
NavData® Alert

!! URGENT !!

Date: 11 September 2018

Subject: Dawei, Myanmar
Dawei (VYDW)
VOR DME Rwy 16 [D16]
VOR DME Rwy 34 [D34]

Cycle 1810

Out Dated Procedure Coding

Jeppesen NavData for cycle 1810, effective 13 September 2018, contains out dated procedure coding at Dawei, Myanmar [VYDW].

THEREFORE, DO NOT USE THE VOR DME Rwy 16 [D16] or VOR DME Rwy 34 [D34] IN CYCLE 1810 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1811, effective 11 October 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

VYDW 1810