



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GFC 500 Owner and Operators
DATE: October 29, 2018
SUBJECT: Amendment to GFC 500 Part 23 AML STC SA01866WI for PA-28 Series Design Changes
CERTIFICATION AUTHORIZATION: AML STC SA01866WI MDL Revision 8

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides instructions for incorporating the following design improvements for the installation of the GFC 500 system in PA-28 series aircraft with AML STC SA01866WI Master Drawing List Rev. 8:

- Updated pitch and roll servo cables
- Revised servo cable wrap instructions
- Clarification regarding cable clamp rotation

PRODUCTS AFFECTED

Piper PA-28 aircraft with GFC 500 systems installed per the GFC 500 Part 23 AML STC SA01866WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.