



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 25 February 2019

Subject: Chihuahua, Mexico
Gen DIV P.A. Roberto Fierro Villalobos Intl (MMCU)
ILS DME 3 Rwy 36R
VOR DME 3 Rwy 36R
Cycles 1902 and 1903

Incorrect Approach Transition Coding

Jeppesen NavData for cycles 1902 and 1903, effective 31 January 2019 and 28 February 2019 respectively, contains incorrect approach transition coding on the ETLEP transition used on the ILS DME 3 Rwy 36R and VOR DME 3 Rwy 36R.

THEREFORE, DO NOT USE ETLET APPROACH TRANSITION IN CYCLES 1902 and 1903 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1904, effective 28 March 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.