



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GMA 342/345 Owner and Operators
DATE: April 3, 2019
SUBJECT: GMA 342/345 System Software Version 2.20
CERTIFICATION AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

GMA 342/345 System Software Version 2.20 includes the following enhancements:

- Improves "passengers always get music 2" option. When configured radio and alert audio will not mute passenger music and volume level will be fixed (instead of adjusted by copilot music volume knob).
- Improves audio filtering for wired telephone input.

PRODUCTS AFFECTED

GMA 342 (011-03520-10) and GMA 345 (011-03520-00) units with System Software Version 2.10 (or earlier) are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.