



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTX 3X5R Owner and Operators
DATE: April 10, 2019
SUBJECT: GTX 3X5R Installed in G1000-equipped PA-46 aircraft
CERTIFICATION AUTHORIZATION: STC SA01714WI

COMPLIANCE

Mandatory: This STC Service Bulletin must be accomplished within the next 5 hours of operation.

PURPOSE

GTX G1000 configuration loader images cause the aircraft cabin pressurization system to not operate correctly. This condition only exists while the aircraft is on the ground and does not affect the operation of the cabin pressurization system while airborne.

PRODUCTS AFFECTED

GTX 3X5R transponder installed in G1000-equipped PA 46-350P/500TP aircraft with GDU software versions between 14.XX and 15.XX are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.