

GARMIN[®]

Navigation Data Alert

DATE: 30 MAY 2019
CYCLE: 1906, Effective 23 MAY 2019 to 20 JUN 2019
SUBJECT: Incorrect Hold Turn Direction

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect hold turn direction.

Airport	Procedure	Error
KPDT	VOR RWY 7 (S07)	The hold turn direction for the missed approach hold at PDT VORTAC should be a right turn.

This alert applies to the 1906 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 1907 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."