



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G5 Electronic Flight Instrument owner/operators
DATE: June 7, 2019
SUBJECT: G5 Electronic Flight Instrument Redundant ARINC 429 Connection
CERTIFICATION AUTHORIZATION: FAA STC SA01818WI, EASA STC 10064473, EASA STC 10060846

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

A redundant ARINC 429 connection can be removed.

PRODUCTS AFFECTED

G5 Electronic Flight Instruments installed using FAA STC SA01818WI, EASA STC 10064473, or EASA STC 10060846 interfaced to the following products is affected:

- GNS 430W/530W series navigator with software version 5.40 or later
- GTN 6XX/7XX series navigator with software version 6.62 or later

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.