



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date:** 12 July 2019

**Subject:** Yangzhou, PR of China  
Taizhou (ZSYA)  
Multiple procedures  
Cycle 1908

*Procedures not in database*

Jeppesen NavData for cycle 1908, effective 18 July 2019, does not contain multiple procedures for Taizhou; Yangzhou, PR of China (ZSYA). The following procedures are not contained in the 1908 data:

**Approach:** RNAV ILS/DME Z RWY 17, ILS/DME Y RWY 17

**STAR:** NIX-92A [NIX92A], NOB-92A [NOB92A], ZJ92A [ZJ92A], VMB92A [VMB92A], VMB94A [VMB94A]

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 1909, effective 15 August 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

ZSYA\_1908