

DATE: 05 September 2019

CYCLE: 1909 & 1910 Effective 15 AUG 2019 to 10 OCT 2019

SUBJECT: Incorrect Turn Direction on Missed Approach

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect turn direction on the missed approach:

Airport	Procedure	Error
KLWC	VOR/DME-A (VDMA)	The turn on the missed approach should be a left turn.

This alert applies to the 1909 & 1910 cycles of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 1911 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."