



1200 E. 151<sup>st</sup> Street  
 Olathe, KS 66062  
 913-397-8200

**AVIATION SERVICE DOCUMENT NOTIFICATION**

**TO:** Garmin GTX 33X/3X5(R) Owner and Operators  
**DATE:** October 10, 2019  
**SUBJECT:** Approval of GTX 3X5(R) main software version 2.54, GTX 3X5D(R) installation approval, new interfaces, and new models added to the AML  
**CERTIFICATION AUTHORIZATION:** STC SA01714WI and EASA STC 10060873

**COMPLIANCE**

Optional: This STC Service Bulletin may be incorporated at the owner’s discretion and is not warranty reimbursable.

**PURPOSE**

This STC Service Bulletin provides notification of an update to STC SA01714WI and EASA STC 10060873, GTX 33X and GTX 3X5(R) with ADS-B AML STC. Major details of the update are:

- Updated GTX 3X5(R) Main software to v2.54 for all models



**NOTE**

GTX 3X5(R) Main software 2.54 provides no gain in unit functionality.

- Added new GTX 3X5D(R) Diversity transponder models
- Approval of GPS 175/GNC 355 interface
- Added additional G1000 GDU software versions for Textron Aviation B58 and A36 models

Under this update, the following models were added to STC SA01714WI.



**NOTE**

*No new G1000 models were added.*

**Table 1. New Non-G1000 Models**

Airplane Make (TCDS Holder)	Airplane Model Designation	TCDS Number
Aviat Aircraft, Inc. (Aviat Aircraft, Inc.)	S-1S, S-1T, S-2, S-2A, S-2B, S-2C, S-2S	A8SO

**PRODUCTS AFFECTED**

GTX 335/335R/345/345R (GTX 3X5(R)) units installed using Part 23 ADS-B AML STC SA01714WI and EASA STC 10060873 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin’s authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.