



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G5000 Owner and Operators
DATE: October 31, 2019
SUBJECT: BIAS HEATER FAIL CAS message design change for G5000 in Textron Aviation Inc. Model 560XL

CERTIFICATION AUTHORIZATION: STC ST01918WI

COMPLIANCE

Recommended: Garmin recommends the incorporation of this STC Service Bulletin at the next scheduled service interval.

PURPOSE

The BIAS HEATER FAIL CAS message will not appear in the G5000 CAS window when the Panel Light Switch is On and the Rotary Test Switch is in the ANNU position.

PRODUCTS AFFECTED

G5000 Integrated Flight Decks installed in Textron Aviation Inc. (Cessna) Model 560XL under STC ST01918WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.