

## **SERVICE ADVISORY**

**NO.: 1989 Rev A**

**TO:** G1000 NXi equipped Piper M350/M500 and G3000 equipped M600 Owners and Operators  
**DATE:** November 26, 2019  
**SUBJECT:** Loss of ILS Auto Transition

---

### **PRODUCTS AFFECTED**

The following products are affected:

#### **NOTE**

Software loader card part numbers are displayed on the splash screen.

- G1000 NXi equipped Piper M350 with software image part numbers 006-B2783-01 through 006-B2783-04
- G1000 NXi equipped Piper M500 with software image part numbers 006-B2785-01 through 006-B2785-04
- G3000 equipped Piper M600 with software image part numbers 006-B2039-12 through 006-B2039-15

### **ISSUE**

The AFCS will not automatically capture the ILS and the CDI will not auto transition to ILS.

### **ACTION**

To capture ILS manually switch the NAV source to LOC.

### **RESOLUTION**

This will be fixed in a future software image part number release.