



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GSR 56 Owners and Operators
DATE: February 5, 2020
SUBJECT: GSR 56 Mod 1
CERTIFICATION AUTHORIZATION: TSO

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended for installations with the internal heater enabled.

PURPOSE

The GSR 56 includes an optionally enabled internal heater that is specified for operation at temperatures below -20°C. The activation of the internal heater may cause the GSR 56 to power off for approximately one minute.



NOTE

This could result in CAS or system failure messages and/or indications of “Waiting” on the Iridium Status page.

The GSR 56 functions as intended after the power off.

PRODUCTS AFFECTED

The following units are affected only when the internal heater is enabled:

Table 1. Products Affected

Model	Appliance P/N
GSR 56	011-02268-00
GSR 56 Enhanced	011-02268-01
GSR 56H	011-02268-10
GSR 56 Harsh Environment	011-02268-50

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.