

GARMIN[®]

Navigation Data Alert

DATE: 10 February 2020
CYCLE: 2002, Effective 30 JAN 2020 to 27 FEB 2020
SUBJECT: Incorrect Missed Approach Turn Direction

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect turn direction on the missed approach:

Airport	Procedure	Error
13K	VOR/DME RWY 18 (D18)	The missed approach was incorrectly coded with a right turn to EUREK int. The correct missed approach turn to EUREK int should be a left turn.

This alert applies to the 2002 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure in any manner

RESOLUTION

The procedure will be corrected in the 2003 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."