



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin GTS Processor GTS 825/GTS 855/GTS 8000 Owner and Operators  
**DATE:** March 24, 2020  
**SUBJECT:** GTS Processor Software Version 3.14.1 for Non-GX000 Integrated Flight Deck Installations Only  
**CERTIFICATION AUTHORIZATION:** TSO Authorization

---

### **COMPLIANCE**

Recommended: Garmin recommends the incorporation of this Service Bulletin at the next scheduled service interval.

### **PURPOSE**

GTS Processor software version 3.14.1 fixes an issue where some ADS-B traffic intruders may not be displayed when over 200 ADS-B intruders are within range.



### **NOTE**

*Active TCAS surveillance is not affected by this issue.*

### **PRODUCTS AFFECTED**

All GTS Processor GTS 825/GTS 855/GTS 8000 units (011-02571-0( )) with software version 3.14 (or earlier) and interfaced to a GTN 6XX/7XX, GNS 4XX(W)/5XX(W), GNS 480, G500, G500H, G600, GMX 200, MX20, or other 3<sup>rd</sup> party flight display systems are affected.

The current GTS Processor software version can be viewed by using the GTS Processor Install Tool (refer to the Modification Instructions section of this bulletin), on the software label adjacent to the GTS Processor serial number tag (for installations unable to electronically display the software part number), or on the display for those units interfaced through HSDB (e.g. GTN 6XX/7XX, G500, G500H, and G600).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.