

SERVICE ADVISORY

NO.: 2043 Rev A

TO: Embraer Prodigy® Flight Deck 100 with G1000 NXi Owners and Operators
DATE: March 23, 2020
SUBJECT: Increase Speed Aural Alert

PRODUCTS AFFECTED

Embraer Prodigy® Flight Deck 100 with G1000 NXi with System Software Version 3643.00 (and earlier) are affected.

ISSUE

The Increase Speed Aural alert does not play.

ACTION

Be aware the Increase Speed Aural alert does not play.

RESOLUTION

This issue has been corrected in System Software Version 3643.01.