



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G5000 equipped Textron Aviation Model 400A Beechjet Aircraft Owners and Operators  
**DATE:** April 13, 2020  
**SUBJECT:** Yaw Servo Cable Clamp Inspection  
**CERTIFICATION AUTHORIZATION:** AML STC ST01821WI

---

### **COMPLIANCE**

**MANDATORY:** Compliance with this STC service bulletin is mandatory at next opportunity or maintenance event, not to exceed 200 flight hours.



### **NOTE**

*Compliance with Garmin Service Bulletin 1714 does not substitute compliance with this service bulletin.*

### **PURPOSE**

Yaw servo cable tension may change due to cable clamp movement

### **PRODUCTS AFFECTED**

Textron Aviation Model 400A Beechjet aircraft modified with the Garmin G5000 Integrated Flight Deck (STC ST01821WI Master Drawing List, Revisions 1 through 6) are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.