



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owners and Operators
DATE: April 22, 2020
SUBJECT: GI 275 Multi-function Instrument Software Version 2.04
CERTIFICATION AUTHORIZATION: AML STC SA02658SE

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification of STC SA02658SE Master Drawing List revision 3 update.

Updates include:

- Clarifications, improvements, and corrections to the STC Installation Manual.
- Added a configuration to disable Course Selection output as well as a configuration to receive Selected Course from the Navigator or an interfaced EFIS when the GI 275 is a secondary navigation indicator.
- Added improvements for installations in aircraft panels with higher vibration.
- Corrected the red band airspeed marking for advanced Vne configurations.
- Corrected Database system message on CDI only configurations.
- Corrected ADC system message when installed with TXi that has RVSM enabled.
- Corrected the flight director display for the Century 2000, IV, and 41 Autopilots. *Refer to Garmin Service Letter 2054.*
- Additional eligibility of the Citation 525 aircraft models to install a GI 275 to serve as a secondary HSI or as a backup display for navigational functions.

PRODUCTS AFFECTED

GI 275 Multi-function Instrument installed under the GI 275 Part 23 AML STC SA02658SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.