



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 11 August 2020

Subject: Makassar, Indonesia
Sultan Hasanuddin (WAAA)
Multiple procedures
Cycle 2009

Instrument Approach Procedures unusable

Jeppesen NavData for cycle 2009, effective 13 August 2020, contains incorrect data for Sultan Hasanuddin; Makassar, Indonesia (WAAA). NOTAM A1710/20 was received after the ICAO specified date for aeronautical information publication. As a result, the approach procedures listed below should not be used.

- ILS OR LOC RWY 13
- VOR RWY 03
- VOR RWY 21
- ILS OR LOC RWY 03
- ILS OR LOC RWY 21
- RNP RWY 21

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2010, effective 10 September 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Makassar, Indonesia (WAAA) 11-1 through 13-4 charts dated 07 AUG 20 (effective 13 August 2020) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.