



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G600 TXi Owners and Operators  
**DATE:** September 4, 2020  
**SUBJECT:** G600 TXi EDM (Emergency Descent Mode)

---

### **COMPLIANCE**

Recommended: Compliance with this service bulletin is recommended.

### **PURPOSE**

The G600 TXi EDM target airspeed may not be accurate when switching airspeed configuration types.

### **PRODUCTS AFFECTED**

G600 TXi systems installed in Daher/Socata TBM 700/850 Series aircraft with all of the following are affected:

- A GDU 1060 or GDU 700P/L PFD with Software Version 3.03 or earlier
- A GFC 600 Autopilot

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.