

GARMIN[®]

Navigation Data Alert

DATE: 08 September 2020
CYCLE: 2009 & 2010, Effective 13 AUG 2020 to 08 OCT 2020
SUBJECT: Incorrect Holding Course

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect holding course:

Airport	Procedure	Error
CYVO	ILS RWY 18 (I18/L18)	The hold at YVO VOR/DME has an incorrect inbound course of 003 degrees. The correct holding course is 183 degrees.

This alert applies to the 2009 & 2010 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 2011 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."