



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 20123 Rev A

TO: GTX 3x5(D) Owners and Operators
DATE: November 13, 2020
SUBJECT: Squat Switch

PRODUCTS AFFECTED

All GTX 3x5(D) panel-mount products interfaced to a squat switch installed in non-rotorcraft airframes are affected.

ISSUE

The GTX 3x5(D) defaults to airborne mode for five seconds after startup. This causes the flight timer to increase for five seconds each startup.

ACTION

No pilot action.

RESOLUTION

This will be fixed in a future software release.

© 2020 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.