



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owner and Operators
DATE: June 15, 2021
SUBJECT: GI 275 Multi-function Instrument Software Version 2.32
CERTIFICATION AUTHORIZATION: STC SA02658SE MDL Revision 11

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended for all HSI installations that are interfaced to a Garmin GTN or GNS navigator.

PURPOSE

This STC Service Bulletin provides notification of STC SA02658SE Master Drawing List revision 11 update.

This update includes GI 275 Multi-function Instrument Software Version 2.32:

- New GSB 15 USB Type-C variants for installation and interface with the GI 275
- New Mode 3 Transponder Control page for MFD and Standby ADI/MFD units interfaced with a GTX 345/345R
- New ARINC 429 interface with the GDU 620 to provide flight director and autopilot modes when the GI 275 is interfaced to the GFC 500
- Approved a discrete switch input for the GPSS/HDG and made the touch button more accessible
- Removed the internal battery requirement on GI 275 -10 and -20 ADI units
- Approved third party analog and composite navigator interfaces with the GI 275 ADI
- Removed the displayed distance value on the HSI when an ILS is tuned and a GPS flight plan is loaded (described in Garmin Service Advisory 20132)

PRODUCTS AFFECTED

GI 275 Multi-function Instrument systems installed under the GI 275 Part 23 AML STC SA02658SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.