



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 18 August 2021

Subject: Dien Bien, Vietnam
Dien Bien (VVDB)
LAITU 2A [LAIT2A]
LADON 2A [LADO2A]
Cycle 2108

Procedure coding incorrect

Jeppesen NavData for cycle 2108, effective 12 August 2021, contains incorrect data for airport: Dien Bien; Dien Bien, Vietnam (VVDB). Departure procedures **LAITU 2A [LAIT2A]** and **LADON 2A [LADO2A]** contain incorrect data and should not be used.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2109, effective 09 September 2021. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Dien Bien, Vietnam (VVDB) 10-3 chart dated 2 OCT 20 (effective 08 Oct 2020) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VVDB_2108