



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 13 August 2021

Subject: Kuala Lumpur, Malaysia
Kuala Lumpur Intl-Sepang (WMKK)
ILS or LOC Rwy 15
ILS or LOC Rwy 33
Cycle 2108

Procedures missing from database

Jeppesen NavData for cycle 2108, effective 12 August 2021, contains incorrect data for Kuala Lumpur Intl-Sepang; Kuala Lumpur, Malaysia (WMKK).

Procedures **ILS or LOC Rwy 15** and **ILS or LOC Rwy 33** are missing from database.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2109, effective 9 September 2021. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

WMKK_2108