



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

****MANDATORY****
SERVICE BULLETIN
NO.: 2193 Rev. A

TO: Garmin G5 Electronic Flight Instrument Aircraft Owners and Service Centers
DATE: September 16, 2021
SUBJECT: G5 Airspeed Calibration

PRODUCTS AFFECTED

Garmin G5 Electronic Flight Instruments purchased or installed since May 2021 listed in the link below are affected.

<https://support.garmin.com/en-US/aviation/faq/hCwRzXXaMS8L6yQ2tW80w7/>



NOTE

Serial numbers can be checked in Configuration Mode.

To enter configuration mode and view the serial number:

1. Hold down the knob while applying power to the G5.
2. Select Device Information.
3. Select SFD, SFD1, or SFD2.



© 2021

Garmin Ltd. or its subsidiaries

All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.

PURPOSE

Some G5 Flight Instruments may show an incorrect airspeed.

DESCRIPTION

This service bulletin contains instructions to return the affected product to Garmin.

COMPLIANCE

Mandatory

APPROVAL

N/A

REFERENCES

N/A

MANPOWER

One (1) hour.

WARRANTY INFORMATION

Modification of affected units is covered under the factory warranty. The unit must be returned to Garmin for modification.

For Garmin Dealers only, warranty labor costs to remove/install the unit are reimbursable for Type Certificated and Light-Sport aircraft installations with a deadline of March 31st, 2022 - after which the labor costs will no longer be reimbursable.

To ensure proper reimbursement when completing the warranty claim, indicate the following:

- Indicate compliance with Garmin Service Bulletin 2193
- G5 unit serial number

INSTRUCTIONS

If the G5 product is affected:

- a. For certificated aircraft, contact your local Garmin Aviation Dealer for an RMA.
- b. For experimental aircraft, contact Garmin Product Support.

Make a logbook entry indicating compliance with Garmin Service Bulletin 2193.

MATERIAL INFORMATION

N/A