



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GFC 600H Owner and Operators
DATE: October 6, 2021
SUBJECT: Installation of GFC 600H Yaw Servo Bracket in Bell Helicopter Model 505
CERTIFICATION AUTHORIZATION: STC SR01961WI

COMPLIANCE

MANDATORY: This STC Service Bulletin is mandatory and must be implemented within 12 months from the date of issue.

PURPOSE

Specified rivet material (aluminum) is not compatible with carbon fiber reinforced plastic and will lead to galvanic corrosion on contact with the frame. This Mandatory STC Service Bulletin provides instructions to replace yaw servo bracket fasteners.

PRODUCTS AFFECTED

GFC 600H systems installed under the GFC 600H Bell 505 STC SR01961WI, Master Drawing List Revisions 1 through 3 in Bell Helicopters Model 505 (trade name *Jet Ranger X*) are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable, with a deadline of October 31, 2022.



NOTE

New installations completed after October 6, 2021 are not eligible for warranty reimbursement.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.