



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 21123 Rev A

**TO:** G500/G600 TXi Owners and Operators  
**DATE:** November 18, 2021  
**SUBJECT:** GPS Approach Mode

---

### PRODUCTS AFFECTED

G500/G600 TXi products with software versions 3.10 and later, interfaced to a GNS 4XX/5XX WAAS navigator capable of GPS approaches and a DFC90 digital autopilot are affected.

### ISSUE

The G500/G600 TXi does not allow the DFC90 to properly arm and activate GPS approach mode.

### ACTION

Be aware the system does not allow coupled precision RNAV approaches.



### **NOTE**

ILS/LOC/VOR approaches work as intended.

### RESOLUTION

This issue will be fixed in a future G500/G600 TXi software release.

© 2021 Garmin Ltd. or its subsidiaries.

This work is licensed under a  
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).