



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 20123 Rev B

TO: GTX™ 3x5(D) Owners and Operators
DATE: December 22, 2021
SUBJECT: Squat Switch
REVISION B: Added Resolution

PRODUCTS AFFECTED

All GTX 3x5(D) panel-mount products interfaced to a squat switch installed in non-rotorcraft airframes are affected.

ISSUE

The GTX 3x5(D) defaults to airborne mode for five seconds after startup. This causes the flight timer to increase for five seconds each startup.

ACTION

No pilot action.

RESOLUTION

This has been fixed in GTX 3x5(D) Main Software Version 2.65.

© 2021 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.