

1200 E. 151st Street Olathe, KS 66062 913-397-8200

SERVICE ALERT

NO.: 21119 Rev B

TO:King Air 300 Series G1000 STC SA01535WI-D Owners and OperatorsDATE:December 10, 2021SUBJECT:Rudder BoostREVISION B:Added Resolution

PRODUCTS AFFECTED

All original G1000 and G1000 NXi configurations installed in Textron Aviation Inc. (Beechcraft) King Air model 300, 300LW, B300, and B300C per STC SA01535WI-D are affected.

ISSUE

The Rudder Boost system may become inoperative when activated in the event of significant reduction or loss of power in one engine.

ACTION

Be prepared for significantly higher rudder pedal forces during single engine operation with rudder boost system inoperative. Refer to the rudder boost system inoperative information in the applicable AFM/AFMS.

RESOLUTION

Contact your local dealer for incorporation of Garmin STC Service Bulletin 21120.

I

I

© 2021 Garmin Ltd. or its subsidiaries. This work is licensed under a <u>Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License</u>.

Service Alert 21119 December 10, 2021 Page 1-1 Revision B