

GARMIN®
Navigation Data Alert

DATE: 28 August 2025
CYCLE: 2508 Effective 07 AUG 2025 to 04 SEP 2025
SUBJECT: Incorrect departure route

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect departure route:

Airport	Procedure	Error
KMCO	FSHUN FOUR DEPARTURE (FSHUN4)	Runways 17L/R and 18L/R have an incorrect flight path. The vectors after BAAIT should proceed directly to FSHUN.

This Data Alert applies to the 2508 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use runways 17L/R and 18L/R in any manner.

RESOLUTION

The procedure will be corrected in the 2509 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION
UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."