



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

UPDATE

Date: 7 August 2025

Subject: Kirkuk, Iraq
Kirkuk Intl (ORKK)
Multiple procedures
Cycle 2508

Procedure coding incorrect

Jeppesen NavData for cycle 2508, effective 7 August 2025, contains incorrect data for Kirkuk Intl; Kirkuk, Iraq (ORKK).

Procedures **ILS Z or LOC Rwy 31, ILS Y or LOC Rwy 31, ILS X or LOC Rwy 31, ILS W or LOC Rwy 31: KK612 (FAF)** coordinates should read: **N35°24'14.474"; E044°25'53.959"**.

Procedure **VOR Z Rwy 13:** Outbound bearing for transition **KIRKUK** should read **280°**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2509, effective 4 September 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jepesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

ORKK_2508