

GARMIN®

SmartCharts Alert 26079

TO: Users of US and Worldwide Garmin Pilot™ Mobile for iOS and Garmin Pilot™ Web

DATE: June 16, 2026

CYCLE: 2606

SUBJECT: Incorrect missed approach minimum climb gradient value for the RNAV (RNP) Y RWY 31L at KPSP

PRODUCT AFFECTED

The Garmin SmartCharts procedure for the RNAV (RNP) Y RWY 31L at KPSP, Palm Springs, CA, shown in Garmin Pilot Mobile iOS and Garmin Pilot Web is affected.

DESCRIPTION

Under the “Adjustments” column for the “Minimums” tab on the SmartChart for this procedure, the Adjustment stating “Capable of minimum climb of 356 feet per NM to 2200” is incorrect.

The value of 356 feet per NM is not correct. Use a minimum climb gradient of 365 feet per NM.

PILOT ACTION

Ensure you can meet the minimum missed approach climb gradient of 365 feet per NM to 2200 for this procedure.

RESOLUTION

This SmartCharts procedure will be corrected in cycle 2607.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to flyGarmin.com and select “Aviation Data Error Report.”