JEPPESEN®
NavData® Alert

!! URGENT !!

Date: **10 August 2018**

Subject: **Pittsfield, Maine**
Pittsfield Mun (2B7)
RNAV (GPS) Rwy 18 [R18] & [P18]
RNAV (GPS) Rwy 36 [R36] & [P36]
Cycle 1809

Cycle 1810 Procedure Coding Changes Released in Cycle 1809 NavData

Jeppesen NavData for cycle 1809, effective 16 August 2018, contains incorrect procedure coding for the RNAV (GPS) Rwy 18 [R18] & [P18] and RNAV (GPS) Rwy 36 [R36] & [P36] procedures.

FAA source for cycle 1810, effective 13 September 2018, made extensive procedural changes that modified the RNAV (GPS) Rwy 18 [R18] & [P18] and RNAV (GPS) Rwy 36 [R36] & [P36] procedures. The cycle 1810 procedural changes were released in the cycle 1809 NavData.

Therefore, the cycle 1809 procedure coding, effective 16 August 2018, for the RNAV (GPS) Rwy 18 [R18] & [P18] and RNAV (GPS) Rwy 36 [R36] & [P36] should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Cycle 1810 NavData, effective 13 September 2018, will contain the correct procedure coding for the RNAV (GPS) Rwy 18 [R18] & [P18] and RNAV (GPS) Rwy 36 [R36] & [P36] procedures. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site.
http://www.jeppesen.com/company/alerts/alerts.jsp

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 1-303-328-4445
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.