# GARMIN

# Navigation Data Alert 26209

**TO:** Users of the Garmin Navigation Database

**DATE:** November 17, 2026

**CYCLE:** 2611 & 2612

**AIRPORT:** LEST - SANTIAGO/ROSALIA DE CASTRO

**LOCATION:** Spain

**SUBJECT:** Procedure with Incorrect Hold Length

---

## PRODUCT AFFECTED

Cycle 2611 & 2612 of the Garmin Navigation Database (effective 29 OCT 2026 to 24 DEC 2026) are affected.

**NOTE**

This Data Alert does not apply to the Jeppesen NavData database.

## DESCRIPTION

The following procedure has an incorrect hold length.

**Table 1.**

| Airport | Procedure | Correction |
|---|---|---|
| LEST | RNP Z RWY 35 (LPV ONLY) | The correct hold length at ROLFI is 1 minute. |

## PILOT ACTION

Use the procedure with caution.

## RESOLUTION

This will be corrected in the 2613 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

*Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.*

*Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."*