GARMIN
Navigation Data Alert

DATE: 29 January 2019
CYCLE: 1901 & 1902, Effective 03 JAN 2019 to 28 FEB 2019
SUBJECT: Incorrect Step-Down Radial on Procedure

DESCRIPTION

Garmin has been made aware that the following procedure has an incorrect radial coded as a step-down point on the approach transition:

Airport	Procedure	Error
MMMZ	VOR/DME 2 RWY 08	The procedure was delivered with an incorrect stepdown radial of 317° on the approach transition. The ARC should be at or above 4000 until radial 302°

This alert applies to the 1901 & 1902 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION
Use the procedure with extreme caution.

RESOLUTION
The procedure will be corrected in the 1903 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."