GARMIN
Navigation Data Alert

DATE: 16 July 2019
CYCLE: 1907 & 1908, Effective 20 JUN 2019 to 15 AUG 2019
SUBJECT: Incorrect Holding Course

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect missed approach holding course:

Airport	Procedure	Error
KCLT	RNAV (GPS) Y RWY 18R (R18RY)	The missed approach hold at STULL waypoint is incorrect. The correct inbound holding course is 72 degrees

This alert applies to the 1907 & 1908 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION
Use the procedure with extreme caution.

RESOLUTION
The procedure will be corrected in the 1909 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."