

GARMIN®

Navigation Data Alert 26160

TO: Users of the Garmin Navigation Database
DATE: October 2, 2026
CYCLE: 2609 & 2610
AIRPORT: SAEZ - MINISTRO PISTARINI
LOCATION: Argentina
SUBJECT: Argentina Regular Supplement 227/26 was Received Late

PRODUCTS AFFECTED

Cycle 2609 & 2610 of the Garmin Navigation Database (effective 03 SEP 2026 to 29 OCT 2026) are affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedure is out of date.

Table 1.

Airport	Procedure	Correction
SAEZ	RNP RWY 28	The RNP RWY 28 replaced the RNP RWY 29 due to the runway being shortened for work in progress.

PILOT ACTION

Do not use the procedure.

RESOLUTION

The procedure will be corrected in the 2611 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "Aviation Data Error Report."