JEPPESEN
NavData® Alert

!! URGENT !!

Date: **10 November 2026**

Subject: **Malham, Saudi Arabia**
Malham (OESL)
Multiple procedures
Cycle 2611

Procedure coding outdated

Jeppesen NavData for cycle 2611, effective 29 October 2026, contains incorrect data for Malham, Saudi Arabia (OESL). SUP 040-26 (19 OCT 26) and SUP 043-26 (04 NOV 26) were received after the ICAO specified date for aeronautical information publication.

Following procedures are missing from database:

- RNP Rwy 15
- RNP Rwy 33
- VOR Rwy 15
- VOR Rwy 33

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2612, effective 26 November 2026. Until then an entry will appear in the NavData Change Notices beginning and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.