Navigation Data Alert 26201

TO: Users of the Garmin Navigation Database

DATE: November 10, 2026

CYCLE: 2611

AIRPORT: Multiple

LOCATION: Australia

SUBJECT: Incorrect Runway Length and Slope Information

PRODUCT AFFECTED

Cycle 2611 of the Garmin Navigation Database (effective 29 OCT 2026 to 26 NOV 2026) is affected.

NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following runway lengths are incorrect.

Table 1.

Airport	Runway	Correction
YKKG – KALKGURUNG	Runway 13/31	The correct runway length is 3136 feet.
YBOK – OAKEY	Runway 14/32	The correct runway length is 5600 feet.
YWCK – WARWICK	Runway 09/27	The correct runway length is 5381 feet.
YTHN – THUNDERBOX	Runway 07/25	The correct runway length is 6234 feet.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."

GARMIN

Navigation Data Alert 26201

The following runway slope information is out of date.

Table 2.

Airport	Runway	Error
YWKS – WILKINS RUNWAY	Runway 09T/27T	Incorrect runway slope
YTWB – TOOWOOMBA	Runway 06/24	
YWSL – WEST SALE	Runway 14/32	
YIVL – INVERELL	Runway 22	
YBRY – BARIMUNYA	Runway 28	

PILOT ACTION

Use the runways with caution.

RESOLUTION

This will be corrected in the 2612 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."